## State Of Maryland 2019 Bond Initiative Fact Sheet

1. Name Of Project							
Temple Hills Swim Club Pool Renovation							
2. Senate Sponsor	3. House Sponsor						
Griffith	D. Barnes						
<b>4. Jurisdiction</b> (County or Baltimore City)	5. Requested Amount						
Prince George's County	\$45,000						
6. Purpose of Bond Initiative							
the acquisition, planning, design, construction, repair, renovation, reconstruction, site improvement, and capital equipping of a pool at the Temple Hills Swim Club							
7. Matching Fund							
Requirements:	Type: The matching fund may consist of real property.						
Equal	The matching fund may consist of real property.						
8. Special Provisions							
[ ] Historical Easement	[ X ] Non-Sectarian						
9. Contact Name and Title	Contact Ph#	Email Address					
Dawn Dominguez	301-894-5308	dawnd7@verizon.net					
10. Description and Purpose of Organization (Limit length to visible area)							

The Temple Hills Swim Club (THSC) is an asset to the community. Its purpose is to provide a safe place for members/guests to enjoy outdoor recreation and to relax/mingle and meet neighbors. THSC is managed/operated by its members who pay yearly membership dues. Members include racially/ethnically diverse families/individuals and members of the military/first responders. Dues are assessed to maintain/operate the 25-meter length pool. Military members/first responders are given membership discounts. THSC is open to the general public to visit as guests and to participate in family-style parties, swim lessons and day camps. THSC sponsors a swim team that participates in the Prince-Mont League and gives neighborhood children an opportunity to swim competitively. THSC has participated in

the Strive 2 Tri Program. Program graduates serve as lifeguards and pool operators.

## 11. Description and Purpose of Project (Limit length to visible area)

The THSC Board of Directors is seeking funds for white coat resurfacing of the main swimming pool. Resurfacing is necessary since the current white coat has severely deteriorated causing excessive water leakage from the pool & huge water bills. PG County inspectors are advising us to replace the white coat. Fundraisers generally are used to generate funds for large purchases/maintenance issues. However, even after several years of intense fundraising efforts, funding is inadequate for white coating the pool. The size of the pool is 6750 sq. ft. The pool serves 4,000 people & employs 15-20 lifeguards/pool operators over the summer. In preparation for application of new bond/white kote, the pool will be emptied, cleaned and existing loose, delaminated/damaged plaster will be cut and removed & the interior of the pool will be re-plastered prior to applying the bond kote. The renovation will not change the pool size. No new construction is planned at the site.

Round all amounts to the nearest \$1,000. The totals in Items 12 (Estimated Capital Costs) and 13 (Proposed Funding Sources) must match. The proposed funding sources must not include the value of real property unless an equivalent value is shown under Estimated Capital Costs.

12. Estimated Capital Costs							
\$45,000							
\$45,000							
13. Proposed Funding Sources - (List all funding sources and amounts.)							
\$45,000							
\$45,000							

14. Project Schedule (Enter a date or one of the following in each box. N/A, TBD or Complete)										
Begin Desi	ign	<b>Complete Design</b>		Design	<b>Begin Construction</b>		n	<b>Complete Construction</b>		
					4/10/	2019		5/1/2019		
15. Total Private Funds and Pledges Raised			Pe	16. Current Number People Served Annu Project Site		nually at Serve		umber of People to be ed Annually After the ect is Complete		
5000.00	4000 members and			ers and	public	4000 members and public guests				
18. Other	State (	Capita	al Gra	ants to Re	cipien	ts in the Past	15 Yea	nrs		
Legislativ	ve Sess	ion	Aı	Amount		Purpose				
None										
								1		
19. Legal I	Name a	and A	ddre	ss of Gran	itee	Project Add	ress (If	f Different)		
Temple Hills Swim Club, Inc. 5400 Henson Drive Temple Hills, MD 20757					P.O. Box 1213 Temple Hills , MD 20757-1213					
20. Legislative District in Which Project is Located 25 - Prince George					orge's County					
21. Legal S	Status	of Gr	antee	(Please C	heck (	One)				
Local Govt. Fo		For I	or Profit		Non Profit		Federal			
[ ]		[ }	[X]		[ ]		[ ]			
22. Grantee Legal Representative					23. If Match Includes Real Property:					
Name:	NA				Has An Appraisal Been Done?		Yes/No			
Phone:						Yes				
Address:						If Yes, List Appraisal Dates and Value				
						07/01/202	18	264800.00		

24. Impact of Pro	24. Impact of Project on Staffing and Operating Cost at Project Site								
Current # of Employees	Projected # of Employees	Curr	ent Operating Budget		Projected Operating Budget				
15-20	15-20		50000.00	50000.00					
25. Ownership of	f Property (Info Requ	ested by	Treasurer's Offic	e for bond	purposes)				
A. Will the grante	A. Will the grantee own or lease (pick one) the property to be improved?  Ow								
B. If owned, does the grantee plan to sell within 15 years?									
C. Does the grante	thers?	No							
D. If property is o	wned by grantee any sp	pace is to	be leased, provide	e the followi	ng:				
	Lessee	Terms of Lease		Cost Square Covered Footage by Lease Leased					
	NA								
E. If property is le	eased by grantee - Prov	ide the fo	llowing:						
Na	ame of Leaser	Length of Lease	Options to Renew						
	NA								
26 Duilding Com	ama Faataza								
26. Building Squ				NT A					
Current Space G		NA NA							
New GSF NA									

## 27. Year of Construction of Any Structures Proposed for Renovation, Restoration or Conversion

1966

## 28. Comments

The THSC needs the State grant of \$45K to replace the white coat on our pool. The pool has been in need of a new white coat for several years, but the club hasn't had the money necessary to make this repair. The monies raised each year by the clubs activities and by additional fund raisers are needed for the normal operation of the old (50+ years) pool and its facilities. Our situation became serious the last two summers when the severely deteriorated white coat caused leaks that resulted in excessive water consumption at the pool and huge water bills. PG County inspectors also noted the situation and said we should have the white coat replaced. THSC acquired 4 quotes for replacement of the white coat. The quotes fall in the range of \$40-65K. We have selected the company that gave us a \$43K quote. The \$45K State grant will cover the labor and materials to prepare the pool for application of the white coat and for the white coat application. Also included is a small amount to cover any cost over-runs that can often incur when unforeseen damage is encountered.